

TO: JAY ELLARD  
OLD BEGA HOSPITAL RESERVE TRUST

ATTENTION:

Job: Old Bega Hospital

Job No: A3585

Date: 2 November 2012.

**SITE INSPECTION REPORT/INSTRUCTION**


Subsequent to our inspection with you today, prior to the preparation & issue of plans for brickwork structural repair we instruct the following remedial works to take place immediately:

- Southern side internal hallway arch to be adequately propped centrally & beneath the articulated / separated brickwork so as to support the brick arch from dislodging or falling until adequate structural repair is performed.

It is important not to try to push the archway brickwork vertically back up with the propping process, but instead provide shoring and propping of the brickwork in its present position only.

Provide adequate parawebbing around the prop across the hallway so as to indicate a temporary repair and no access area.

Copy to:

  
Engineer: